



Great Neck Auto Tech

301 East Shore Rd
Great Neck, NY 11023
Phone: 516-487-4210

09/29/2025
Repair Order #
137419

Repair Order

VILLAGE OF THOMASTON

BEN

2015 Ford Explorer

License: AA7005

VIN: 1FM5K8D84FGC69032

Cellular (516) 779-3851

Eng: 3.5L, V6 (213CI) VIN(8)

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
ANTI-FREEZE COOLANT				***Estimate is for new original equipment Ford water pump. The camshaft timing chain and related components are assumed to be in good working order due to low mileage on engine. However, once disassembled, there may be additional items may be needed.	
COOL	3.00	\$28.00	\$84.00		
Water Pump					
DG1Z 8501-D	1.00	\$167.94	\$167.94		
VALVE COVER GASKET SET					
vcg	2.00	\$130.00	\$260.00		\$0.00
Timing Chain Kit - chains, tensioners, adjusters, guides				WATER PUMP - Remove & Replace - V6, Normally Aspirated - [Includes: R&I Camshaft Drive Chain.]	
ZC-9-0738SBX	1.00	\$700.00	\$700.00		\$2,535.00

RECEIVED BY

SEP 29 2025

Village of Thomaston

Service Advisor: MCCARRICK, BILL

Technician(s):

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.
TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ___ days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ___. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Labor Total:	\$2,535.00
Parts Total:	\$1,211.94
Shop Sup.:	\$0.00
HazMat:	\$0.00

Sub Total:	\$3746.94
Tax Total:	\$0.00
Grand Total:	\$3,746.94
Balance Due:	\$3,746.94



SIGNATURE..... Date.....



www.greatneckautotech.com

Page 1





BIENER FORD

661 NORTHERN BLVD., GREAT NECK, NY 11021


VIN 1FM5K8D84FGC69032

2015 FORD EXPLORER 3.5 ENGINE

We will be replacing the water pump, tensioner and guides along with the serpentine belt. Parts and labor will be \$4271.79. list of part attached on another page

Peter Viskoc

Service Director



VILLAGE OF TOMASTON

Home:

Mobile: (516) 779-3851

Work:

Email:

Sep 24, 2025 08:42 AM

YMMS: 2015 Ford Explorer XLT

Engine: 3.5L Eng

License:

VIN: 1FM5K8D84FGC69032

Odometer:

TYPE	DESCRIPTION	PART #	QTY	PRICE	RATE	HOURS	LINE TOTAL
Labor	WATER PUMP - Remove & Replace V6, Normally Aspirated	-	-	-	\$215.00	12.2	\$2,623.00
Parts	GASKET	AT4Z9H486A	1.0	\$51.98	-	-	\$51.98
Parts	BOLT	F5RZ6A340B	1.0	\$42.35	-	-	\$42.35
Parts	SEAL	BR3Z6C535	4.0	\$28.18	-	-	\$112.72
Parts	SEAL		6.0	\$30.73	-	-	\$184.38
Parts	GASKET		1.0	\$56.50	-	-	\$56.50
Parts	GASKET		1.0	\$50.22	-	-	\$50.22
Parts	SEAL ASSY		1.0	\$32.45	-	-	\$32.45
Parts	ARM		1.0	\$57.38	-	-	\$57.38
Parts	TENSIONER		1.0	\$90.75	-	-	\$90.75
Parts	GUIDE		1.0	\$56.10	-	-	\$56.10
Parts	BELT		1.0	\$146.64	-	-	\$146.64
Parts	GUIDE		1.0	\$39.18	-	-	\$39.18
Parts	GUIDE		1.0	\$40.08	-	-	\$40.08
Parts	PUMP ASY		1.0	\$190.39	-	-	\$190.39
Parts	COOLANT		1.0	\$44.88	-	-	\$44.88
Parts	PARTS CLEANER		1.0	\$5.38	-	-	\$5.38
Parts	OIL CHANGE		1.0	\$100.00	-	-	\$100.00

RECEIVED BY

SEP 29 2025

Village of Thomaston

Labor:	\$2,623.00	
Parts:	\$1,301.38	
Shop Supplies:	\$3.50	
Hazardous Materials:	\$5.00	
Labor Taxes:	\$226.23	N/A
Parts Taxes:	\$112.68	N/A
TOTAL:	\$4,271.79	

without tax: \$3,932.88