

Village of Thomaston
100 East Shore Road
Great Neck, NY 11023
516-482-3110 Fax 516-504-3768

Drainage, Road and Sidewalk Improvements 2022

MILL and RESURFACE

STREET	FROM	TO	LENGTH (FT)	APPROXIMATE WIDTH (FT)	AREA (SF)
Colonial Rd	Windsor Rd	Highland Av	891	27	24,057
Shoreward Rd	IFO 245 Shoreward Dr	(Patch)	15	16	240
Avalon Rd	IFO 4 Avalon Rd	(Patch)	20	16	320
Grosvenor Pl	IFO 6 Grosvenor Pl	(Patch)	45	14	630
9 St. George Rd	IFO 9 St. George Rd	(Patch)	12	10	120
Terrace Dr	IFO 12 Terrace Dr	(Patch)	6	3	18
Windsor Road	Across - 20 Windsor	(Patch)	34	13	442
Crescent Rd & Shoreward Dr		(Patch)	7	7	49
Susquehanna Av & Northern Blvd		(Patch)	20	18	360
IFO 10 Lincoln Rd to Crescent Rd to Windsor Road to Shoreward Drive					10,250

BASE REPAIR – ASPHALT

STREET	ESTIMATED NUMBER OF REPAIRS	TOTAL AREA (SF)
Colonial Rd	(12) 2' x 2' sections	48

CLEANING OF EXISTING CATCH BASINS AND INSTALLATION OF NEW DRAINAGE PIPE

LOCATION	EST. TOTAL LENGTH (FT)	NOTES
IFO 10 Lincoln Rd to Crescent Rd to Windsor Road to Shoreward Drive	410	Pipe to be connected from catch basin to catch basin - (3) catch basins

INSTALLATION OF NEW DRAINAGE PIPE (A) AND MILL and RESURFACE (B)

----- APPROXIMATE -----

(A) STREET	EST. LENGTH (FT)	NOTES
Terrace Dr (IFO 21 Terrace Dr)	72	Attach to catch basin IFO 8 York

----- APPROXIMATE -----

(B) STREET	LENGTH (FT)	WIDTH (FT)	AREA(SF)	NOTES
Valley View Road to Terrace Dr	98	35	3,430	

CATCH BASIN REPAIR

LOCATION	NOTES
Intersection of Crescent Rd & Shoreward Dr	(1) catch basin
IFO 12 Terrace Dr	(1) catch basin

INSTALLATION OF CATCH BASIN

LOCATION	NO. OF CATCH BASINS
4 N. Avalon Rd, 45' North of driveway at curb	1

STAMPED CONCRETE BLOCK DRIVEWAY APRON REPLACEMENT- ITEM 6-DA (Portion within the Right-of Way)

----- APPROXIMATE -----

LOCATION	NO. OF REPLACEMENTS	EST. Total AREA (SF)
4 N. Avalon Rd	1	160

